

News media information 202-418-0500 Internet: http://www.fcc.gov (or ftp.fcc.gov) TTY (202) 418-2555

Report No. SAT-00800

DA No. 11-1398

Friday August 12, 2011

## Policy Branch Information Actions Taken

The Commission, by its International Bureau, took the following actions pursuant to delegated authority. The effective date of these actions is the release date of this Notice, except where an effective date is specified.

SAT-STA-20110520-00093

E S2388

Intelsat License LLC

Special Temporary Authority

Granted in Part / Denied in Part Effective Date: 08/05/2011

On August 5, 2011, the Satellite Division granted, with conditions, special temporary authority to Intelsat License LLC for a period of 30 days to conduct telemetry, tracking, and telecommand operations necessary to effect the drift of the Intelsat 702 space station from the 54.85° E.L. orbital location to the 50.0° E.L. orbital location and to maintain the space station temporarily at 50.0° E.L. using the following frequencies: 3947.5 MHz, 3948.0 MHz, 3952.5 MHz, 3952.0 MHz, 6173.7 MHz and 6176.3 MHz. Additionally, Intelsat is authorized to provide Fixed-Satellite Services during this period in the 3700-4200 MHz, 5925-6425 MHz, 10.95-11.2 GHz, 11.45-11.7 GHz, 12.5-12.75 GHz, and 14.0-14.5 GHz frequency bands after Intelsat 702 arrives at the 50.0° E.L. orbital location.

SAT-STA-20110726-00134

E PAS-2R

Intelsat License LLC

Special Temporary Authority

Grant of Authority Effective Date: 08/11/2011

On August 11, 2011, the Satellite Division granted, with conditions, special temporary authority to Intelsat License LLC for a period of 30 days to continue to perform tracking, telemetry, and telecommand operations with the Intelsat 3R space station to execute end-of-life maneuvers. These maneuvers are intended to boost Intelsat 3R from its current location of 81 W.L. to a disposal orbit with a minimum perigee altitude of 150 km above the geostationary arc. Intelsat is authorized to using the following frequencies for these operations: 4199.0 MHz (horizontal and vertical polarization) and 4198.5 MHz (horizontal and vertical) (space-to-Earth) and 6424.5 MHz (horizontal) and 5925.5 MHz (horizontal) (Earth-to-space).

SAT-STA-20110727-00137

E S2469

Intelsat License LLC

Special Temporary Authority

Grant of Authority Effective Date: 08/05/2011

On August 5, 2011, the Satellite Division granted, with conditions, special temporary authority to Intelsat License LLC for a period of 60 days to continue to conduct telemetry, tracking, and telecommand operations necessary to effect the drift of the Galaxy 26 space station from the 50.75° E.L. orbital location to the 50.0° E.L. orbital location and to maintain Galaxy 26 at 50.0° E.L. using the following frequencies: 4196.5 MHz, 4199.5 MHz, 6315.0 MHz, 4090.0 MHz, 5926.5 MHz, and 6411.0 MHz. Intelsat is also authorized to continue to provide Fixed-Satellite Services via Galaxy 26 in the Ku-band frequencies of 14.0-14.5 GHz and 11.7-12.2 GHz during the drift to the 50.0° E.L. orbital location and after Intelsat 702 arrives at the 50.0° E.L. orbital location.

## INFORMATIVE

SAT-MOD-20101029-00228 S2751 Intelsat New Dawn Company, Ltd.

On July 14, 2011, Intelsat New Dawn Company, Ltd. informed the Federal Communications Commission that the Intelsat New Dawn satellite (S2751) was successfully placed into orbit at its assigned location of 32.8° E.L. and became operational at that location as of July 9, 2011, in accordance with the terms of its FCC authorization. See Letter from Susan H. Crandall, Assistant General Counsel, Intelsat Corporation, to Marlene H. Dortch, Secretary, Federal Communications Commission, dated July 14, 2011. Accordingly, the Satellite Division has determined that Intelsat New Dawn has completed the launch and operation milestone associated with the grant of its space station authorization, IBFS File Nos. SAT-LOA-20080509-00101 and SAT-MOD-20101029-00228. Accordingly, Intelsat New Dawn is no longer required to maintain the bond associated with this grant.

For more information concerning this Notice, contact the Satellite Division at 202-418-0719; TTY 202-418-2555.